



A Tyco International Company

USER SAFETY NOTICE

TO: USERS OF THE SCOTT AIR-PAK 75 SELF CONTAINED BREATHING APPARATUS

WARNING: COMPLETELY READ THIS ENTIRE NOTICE AND FOLLOW THE INSTRUCTIONS. FAILURE TO DO SO MAY RESULT IN FAILURE OF AN END-OF-SERVICE TIME INDICATOR TO ALARM WHICH MAY RESULT IN SERIOUS INJURY OR DEATH.

Scott has received one report of a Vibralert end-of-service time indicator not activating when the air pressure from the cylinder dropped to one quarter of the working pressure. The following instructions will assist you in identifying if your SCBA are involved in this safety notice and assist you in getting them repaired.

IDENTIFICATION:

To determine if your SCBA is included in this User Safety Notice, look at the back of your SCBA's pressure reducer.

Figures 1 and 2 show the Air-Pak 75 reducers with and without adjustable seats. Only the reducers with protruding seats are subject to this notice.




Figure 1 - Air-Pak 75 without adjustable seats





Figure 2- Air-Pak 75 WITH adjustable seats
SUBJECT OF THIS NOTICE

If the manufacture date of your SCBA is between January 23, 2012 and April 15, 2012 you have one of these SCBA. The serial number label on the reducer contains the manufacture date. See instructions below for location of the label and date.

Scott has also become aware that on a limited number of Air-Pak 75 SCBA, manufactured between April 16 and June 7, 2012, the 'O'-rings on the air gage block may wear out in an unacceptably short time. The wear would show up as an air leak at the block that would grow worse over time. The repair and replacement of the 'O'-rings is also part of this notice.



Location of Serial Number Label and manufacture date on Air-Pak 75 reducer



If the manufacture date on your SCBA's reducer is NOT between January 23, 2012 and June 7, 2012 (i.e. earlier or later) your SCBA is NOT subject to this notice. If the manufacture date on your SCBA's reducer is between **January 23, 2012 and June 7, 2012 including those dates, follow the notification procedure below.** If you have any questions, contact Scott Technical Service at 1-800-247-7257, ext. 3379 or through the website www.scottsafety.com.

NOTIFICATION:

Once you have identified that you have SCBA that are included in this notice, complete the following form and either send it to your In-house or Distributor Service Center or email/fax it to SCOTT.

Pressure	Number of Affected Air-Pak 75 SCBA In Your Possession	
	Mfg Dates Jan 23, through Apr 15, 2012	Mfg Dates Apr 16, through June 7, 2012
2.2		
3.0		
4.5		
5.5		
Total		
Form Prepared By (Name)		
Customer Name:		
Customer Address:		
Location of SCBA:		

The Distributor Service Center or Scott will schedule the repair at no charge to you. If you have any questions, contact Scott Technical Service at 1-800-247-7257, ext. 3379 or through the website www.scottsafety.com.

SN 09102012-2 Rev A



Distributed by the
NYS Division of Homeland Security and Emergency Services

**OFFICE OF
FIRE PREVENTION
& CONTROL**

phone 518.474.6746
fax 518.474.3240
email fire@dhses.ny.gov