



Voith Repair Service

Save time and money

Turn to Voith to bring your components and systems back to optimal running condition, allowing you to keep production high while limiting unplanned downtime. Voith offers a repair service on its OEM components and on many pieces of non-Voith equipment, which is backed by an expert engineering and applications staff. Looking for a specific spare part? We keep an inventory of the most high-demand papermaking components in our Appleton, Wisconsin headquarters. In addition, all repaired items are backed by a one year parts and labor "as new" warranty to help you stay on track with your time and your budget.

Local service locations

Voith service and repair work is available at the following North American locations:

United States, Midwest

Appleton, Wisconsin
Tel. +920.731.7724

United States, Southeast

Austell, Georgia
Tel. +920.731.7724

Before



After



Pulper rotors

Rotor/screw repair

- **Pulper rotor** – Beloit, KBC, Andritz, Tampella, Voith
- **HD pulper rotor** – Comer, Kadant, Voith
- **Flat Screen** – Beloit, KBC, Comer, Voith
- **Pressure screen** – Beloit, KBC, AFT, Sunds, Voith/Bird
- **Dewatering screws** – Andritz, Vincent, Voith/Thune
- **Overhauls** – Complete screw press machine overhauls

Assembly repair

- **Rotating assemblies** – All Voith and competitor stock preparation
- **Repairs** – Pressure screen housing repair, screen baskets
- **Gearboxes** – KBC #3 Gearbox, all Voith GV gearboxes
- **Overhauls** – Complete stock prep machines and screw press overhauls

Exchange program

- **Combisorter** – Upper, lower and complete units
- Common rotating assemblies
- Common rotor blades

Stock preparation service

- **As needed** – Millwright services for troubleshooting or needed manpower on a shutdown

Before



After



Press screws

Disk filter service

- **At your mill** – On-site disk filter replacement and optimization services with Voith personnel
- **Voith workshop** – Rescreening, repair and replacement capabilities at Voith's Appleton workshop
- **Non-OEM** – Voith can provide service, repair and replacement sectors for any disk filter

PM refurbishment

- Apron blade
- Slice lip
- Lamella
- Pressure shoe
- Guide assemblies
- Stretcher assemblies
- Threading equipment
- IR emitter
- Vacuum pump
- DuoCleaner
- Unwind and brake assemblies
- Slitter assemblies
- Core chuck
- Rotating assemblies
- DPR valves

Before



After



Combisorter

Before



After



MultiScreen

Voith Group
2200 N. Roemer Road
Appleton, WI 54911

Tel. + 920-731-7724
VPAWrepair@voith.com



voith.com

VOITH

Inspiring Technology
for Generations